

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Assistant Engineer)

1	Name of the officer	:-	Er. Nangbia Tedi
2	Name of the School	:-	Don Bosco School, Itanagar
3	Location with name of Education District/ Sub-District	:-	Don Bosco School, P.B, 153, Jollang Itanagar, 791113
4	Classification of Building as specified in Column 4 of the application for fitness certificate and size.	:-	RCC Frame Structure (G+II).
5	Period for which the certificate is issued	:-	2 (Two) Year from date of issue of the certificate
6	Nature of defects, if any		
	a) Foundation and basement	:-	NIL
	b) Superstructure	:-	NIL
	c) Doors and Windows	:-	NIL
	d) Wood work wrought and put up	:-	NIL
	e) Roof	:-	NIL
	f) Flooring	:-	NIL
	g) Miscellaneous (Cracks, etc.)	:-	NIL
7	Any major defects noticed which will render the building unsafe in any manner	:-	NIL
8	Whether maintenance works have been done properly	:-	Yes
9	Whether the structure is sound or not for conducting classes.	:-	Yes, sound for conducting classes


Note:- 1. The stability of the structure should be examined also with reference for location, altitude, intensity of wind, exposure of flood etc. (2.) Any additional observation if deemed necessary for the certificate may be furnished separately with his certificate.

CERTIFICATE

Certified that the school building was inspected by me on 20/06/2023 and found to be fit to conduct classes for the period of 2 (Two) year for the reason stated above.

Place:- Itanagar

Date :- 20/06/2023


Assistant Engineer,
Itanagar Highway Sub-Division
PWD A.P. Itanagar