



FITNESS CERTIFICATE

To be filled by the inspecting Officer (Executive Engineer)

1	Name of Officer	Er. Hillang Taju
2	Name of School	Don Bosco School, Itanagar
3	Location with name of Education District/Sub-District	Don Bosco School, P.B.153, Jollang Itanagar, 791113
4	Classification of Building as specified in column 4 of the application for fitness certificate and size.	RCC Framed Structure (G+2)
5	Period for which the certificate is issued	2 (Two) Years from date of issue of the certificate.
6	Nature of defects, if any :- a) Foundation and basement b) Superstructure c) Doors and windows d) Wood work, wrought and put up e) Roof f) Flooring g) Miscellaneous (Cracks, etc.)	NILL NILL NILL NILL NILL NILL NILL
7	Any major defects noticed which will render the building unsafe in any manner	NILL
8	Whether maintenance works have been done properly	YES
9	Whether the structure is sound or not for conducting classes.	Yes, Sound for conducting classes


Note:

1. The stability of the structure should be examined also with reference for location, altitude, intensity of wind, exposure of flood etc.
2. Any additional observation if deemed necessary for the certificate may be furnished separately with his certificate.

CERTIFICATE

Certified that the school building was inspected by me on 29/04/2025 and found to be fit to conduct classes for the period of 2 (Two) years for the reason stated above.

Place: **Itanagar**
Date: **29/04/2025**


Executive Engineer
Dept. of Urban Development & Housing
Seppa Division : Seppa
Executive Engineer
Urban Development & Housing
Seppa Division :: Seppa